

Hinweise zu Bodenbelagsarbeiten und Pflege von Bodentanks, Kassetten und Bodensteckdosen

ACHTUNG



Beschädigungsgefahr durch unzureichende Dehnungsfuge!

Sich ausdehnender Bodenbelag ohne ausreichende Dehnungsfuge führt zu Produktschäden!

Bodenbelag am Bauteil des Bodentanks (Kassetten und Bodensteckdosen) spannungsfrei anarbeiten.

Dazu ausreichende Dehnungsfuge mit dauerelastischem Fugenmaterial verfüllen.

ACHTUNG



Beschädigungsgefahr durch Fugenmaterial/Kleber!

Das Eindringen des Fugenmaterials/Klebers in den Bodentank (Kassetten und Bodensteckdosen) führt zu Produktschäden!

Innenraum nach den Bodenbelagsarbeiten gründlich reinigen.

ACHTUNG



Beschädigungsgefahr durch ätzende Reinigungsmittel!

Der Kontakt mit säure-/chloridhaltigen Reinigungsmitteln (z. B. Zementschleierentferner) führt zu Produktschäden!

Sollte die Grundreinigung des Bodens mit diesen Reinigungsmitteln durchgeführt werden, empfehlen wir den Deckel während der Reinigung zu entnehmen. Dabei ist sicherzustellen, dass keine Feuchtigkeit in Rahmen und Gehäuse eindringt.

Sollte der Deckel während der Reinigung im Rahmen verbleiben, sind alle Bauteile inkl. Innenraum gegenüber den ätzenden Reinigungsmitteln (z. B. durch flächiges Abkleben) zu schützen.

Sollten die Bauteile in Kontakt mit ätzenden Reinigungsmitteln kommen, sind diese sowie die Dichtungen mit klarem Wasser zu reinigen.

OBO Bettermann Holding GmbH & Co. KG
P. O. Box 1120
58694 Menden
GERMANY

Customer Service:
Tel.: +49 2373 89 - 17 00
Fax.: +49 2373 89 -12 38
info@obo.de

www.obo-bettermann.com

Building Connections

OBO
BETTERMANN

Instructions for floor covering work and cleaning of floor box, cassettes and floor sockets

ATTENTION



Risk of damage through insufficient expansion joint!

An expanding floor covering without a sufficient expansion joint leads to product damage!

Work the floor covering with no tension up to the floor box (cassettes and floor sockets) component.

To prevent this, fill a sufficient expansion joint with permanent-ly elastic joint material.

ATTENTION



Risk of damage from joint material/adhesive!

Ingress of the joint material/adhesive into the floor box (cas-ettes and floor sockets) can lead to product damage!

Thoroughly clean the interior after floor covering work, should joint material/adhesive have entered. Observe the care infor-mation.

ATTENTION



Risk of damage from caustic cleaning agents!

Contact with cleaning agents containing acids/chlorides (e.g. cement residue removers) will cause damage to the product! Should the basic cleaning of the floor be carried out with these cleaning agents, then the lid should be removed during clean-ing. Ensure that no moisture can ingress into the frame and housing.

Should the lid remain in the frame during cleaning, then all the components, including the interior, should be protected against the caustic cleaning agents (e.g. by widespread masking).

Should the components come into contact with caustic clean-ing agents, then they and the seals should be cleaned with clear water.

OBO Bettermann Holding GmbH & Co. KG
P. O. Box 1120
58694 Menden
GERMANY

Customer Service:
Tel.: +49 2373 89 - 17 00
Fax.: +49 2373 89 -12 38
info@obo.de

www.obo-bettermann.com

Building Connections

OBO
BETTERMANN